DPS6 Related Complaints ODI VOQ's and Ford TREAD-Reportable Reports data generated 12/2/13

Number of Reports by Source System and Safety Concern

Related (Multiple Items)

Count of ECI Record IO Safety Concern	Source System								
	AWS	GCOIS Ford	MORS\ CUDL	FMC360	001	OGC	LMMS	Grand Total	
FATALITY Accident						1		1	
Anxiety	1			1		1		2	
Makes sick				1		•		1	
Headache				1				1	
Injury				4		1		5	
accident w/ 2 inj					1	,		1	
Accident w/ 1+ injuries				1	,			1	
Accident w/ 1 inj				-		1		1	
Accident w/ 1 inj and Fire	Endan.					1		,	
accident			6	3		32		41	
almost accident)			•	27	OL,		27	
caused safety issue with traffic	1				1			4	
Smoke U'hood		10	3	4	,			47	
Sparks U'hood	5	, •	Ū	1				47	
Harness melted	3			•				1	
Overheat	} _							2	
towed in	4				۰			4	
No 'Adverse' outcome		5	18	7	121	- 1	20	9	
Grand Total	38	15	27	23	218	38	30 30	243 389	

Memo: summary of allegations

Alleged fatality incidents 1

Alleged injury incidents 46

Alleged TREAD fires 51

Memo: summary of fatality incident

OGC D082421 '11 Fiesta incident May '13 Transmission stalled and caused an accident. Her son was going around a corner at 60 mph when it happened. The son died on impact. We requested additional information, but received no response.